Puerto Rico Electric Power							Generation I	Directorat	e		
Authority							Current Status of PREI	PA Generat	tion Fleet		
		_	1		Data affect	Detection	REV: NOV	2, 2021			
Power Station	Unit	Capacity (MW)	Available Capacity	Condition	Date of last major maintenance	Date of last major maintenance	Person in charge of attending findings	NME (Million)	FY22	FY23	Currents Status / Action Plan / Comments
							PREPA's Base	Generatio	n		
	CT 5 STM 5	160 60	150 50	Available Available		Apr-11		\$40.00	\$40.00		Major overhaul; Proposed dates: January 15, 2022; taking moderate risks. Approximate cost \$40 million including LTSA (Long Term Services Agreement). Major overhaul; Proposed dates: January 15, 2022. Verifying delivery of steam turbine parts is a critical path.
	CT 6	160	120	Available							Major overhaul; Proposed date: February 2023; Approximate cost \$30 million.
	STM 6	60	0	Not Available	Sep-13	Jun-10		\$33.00		\$33.00	Generator Instrumentation Problems (field Ground) . Forecast November 4 . Major overhaul; Proposed date: February 2023.
San Juan	7	100	70	Available	Aug-08	Aug-08	Eng. Alejandro Castillo / Plant Manager	\$18.00		\$18.00	Unit Return to service on October 19, 2021. Turbine rotors have expired hours for major repair (over 70K hours). Approximate repair cost \$5 millions. Boilers Repairs (10 million) needed. Major inspection date to be determined. Unit in limited use (8%) according to EPA MATS (Mercury and Air Toxic Standards).
	8	100	0	Not available	Nov-10	Nov-10		\$18.00		\$18.00	Boiler pipe breakage problems, steam leaks and feedwater heater #6 problems. Limited use unit (8%) according to EPA (MATS). Boiler air leaks. Approximate cost of boiler repairs and auxiliary equipment, \$18 million including new boiler piping.
	9	100	0	Not Available	Nov-19	Aug-12		\$2.00		\$2.00	Programmmed outage 7 days (28/oct-3 nov):coolers replacement, BFP9-1 and 9-2 inspection, condenser cleaner etc.DEMI (Demineralized) water production problems. Temporary water production plant of the Central (RO) faces operational problems. In the process of completing the installation of a new permanent DEMI plant.
	10	100	0	Not available	Sep-09	Sep-09		\$17.00	\$17.00		Low pressure turbine fault. Unit not available since the end of 2015. Returning the unit to service entails an approximate investment of \$16 million and an estimated duration of the works, 6 months.
	1	85	0	Not available	Apr-08	Apr-08		\$10.00		\$10.00	Limited use unit EPA (MATS). Boiler air leaks, requires replacement of boiler piping. Generator has major stator failure and requires turbine work.
	2	85	0	Not available				\$15.00		\$15.00	Limited used unit EPA (MATS). Faulty unit generator; The unit's Main Power Transformer is used as an output transformer for new MPA FT-8.
Palo Seco	3	216	0	Not Available	Nov-09	Nov-09	Eng. Antonio Kalil / Plant Manager	\$7.00		\$7.00	Forced Outage 31 Oct2 Nov: Economizer (boiler) tube failure . Unit return online for November 2 2021. It is required to purchase boiler tube and economizer panels for approximately \$5 million and repair auxiliary equipments, for fiscal year 2022-2023. Unit out of service; boilers tubes failure, return to service november 2 2021.
	4	216	140	Available	May-09	Jun-19		\$3.00	\$3.00		Unit online. Forced outage last month due to oil leak through control wiring. High pressure differential on the air preheaters. Unit return to service on Sunday, October 10, 2021. Environmental outage rescheduled for December 2021, after Costa Sur 6 return to service. Work will be carried out on the boiler and replacement of the air pre-heater baskets.
	1	450	375	Available	Feb-12	Dec-08		\$20.70	\$19.00	\$1.70	Boiler air in leakages. Major repair rescheduled for January 2022, after the entry of Costa Sur 6. Major works, environmental outages, boiler work and replacement of turbine rotors for an approximate \$18 millions.
Aguirre Steam Plant	2	450	375	Available	Mar-10	Dec-19	Eng. Alexis Cruz / Plant Manager	\$2.35		\$2.35	Unit return online october 27 -2021; programmmed outage to correct Feed water control valve issues. In addition, correct boiler air in leakages and air preheaters cleaning. This action eliminated actual limitation. Unit outage begining on October 11 until october 27 2021. Beginnig the procurrement process to repair the Exitation System next year.
	5	410	410	Available	Jul-13	Jul-13	- Eng. Miguel Beauchamp/	\$20.80	\$1.80	\$19.00	Main steam piping failure on September 13, 2021. Unit return service on Wednesday, October 6, 2021. Major outage (boiler, environmental maintenance and replacement of turbine rotors) scheduled for October 2022. Approximate cost \$15 million.
Costa Sur	6	410	0	Not available	Sep-12	Feb-21	Plant Manager	\$6.70	\$5.00	\$1.70	Low pressure turbine failure (LP turbine failure) after major unit repair including these rotors for \$20 million. Rotors were shipped to the US workshop by ship during the week of September 20-27. Findings report is expected for October 18, 2021. Unit expected delivery unit January 15, 2022 at an approximate cost of replacement of damaged parts of \$5 million.
Total PREPA Base Generation		3162	1690	53.45%				\$213.55	\$85.80	\$127.75	Available

Puerto Rico							Generation I	Directorat	9		
Authority							Current Status of PRE	PA Generat	ion Fleet		
							REV: NOV	2, 2021			
Power Station	Unit	Capacity (MW)	Available Capacity	Condition	Date of last major maintenance	Date of last major maintenance	Person in charge of attending findings	NME (Million)	FY22	FY23	Currents Status / Action Plan / Comments
							PREPA's Reserve G	eneration	Fleet		
	I-1	50	48	Available CC		(4,000)		\$1.00	\$1.00		Hot gas path inspection \$1M, April 2022.
	I-2	50	48	Available SC		(2,841)		\$1.00	\$1.00		Inlet filters Clogged. Hot gas path inspection scheduled for June 2022.
	I-3	50	50	Available		(11,392)		\$2.50	\$2.50		Major inpection scheduled for January 2022. \$2.5M
	I-4	50	0	Not Available		(1,574)		\$2.00		\$2.00	PT Repair ; Minor outage october 20 -return unit online for nov 5
Aguirre Combined Cycle	ST-1	96	0	Not Available			Eng. Harry Velázquez / Plant Manager	\$1.00		\$1.00	unit off line october 19; water line repair to cooling tower ; Condenser fouling and air in leakages.
	II-1	50		Not available			r lant Wanager	\$2.00		\$2.00	MPT 2-1, 2-2 failure.
	II-2	50		Not available				\$2.00		\$2.00	MPT 2-1, 2-2 failure. Start up tests.
	II-3	50	30	Available		(1,307)		\$1.00		\$1.00	Repair coolers fan radiators
	II-4	50		Not available		(3,637)		\$1.70		\$1.70	Stand by Transformer fail. Hot gas path inspection and spare rotor \$1.7M.
	ST-2	96		Not available				\$2.00		\$2.00	MPT 2-1, 2-2 failure. Start up tests.
Total Aguirre CC		592	176	29.73%				\$16.20	\$4.50	\$11.70	Availability
DAGUAO	1-1	21	19	Available				\$2.00	\$2.00		Mayor Outage Repair
	1-2	21	17	Available				\$2.00	\$2.00	41.00	Mayor Outage Repair
AGUIRRE	2-1 2-2	21	20	Not available				\$4.00	ć2.00	\$4.00	Unit requires major turbine repair and a complete generator assembly.
		21	20	Available				\$2.00	\$2.00		Mayor Outage Repair
	1-1 1-2	21	18	Available Not available				\$2.00 \$2.30	\$2.00	\$2.30	Mayor Outage Repair
-	2-1	21	0	Not Available				\$2.00	\$2.00	ŞZ.30	Mayor Outage Repair and Generator breaker replacement Mayor Outage Repair
PALO SECO	MPA 1	23	0	Not available				\$0.10	\$0.10		Environmental air permit. Contract awarded to perform environmental acceptance tests. Waiting for EPA
TALO SECO	MPA 2	23		Not available			Eng. José Vázquez HG Head Division /	\$0.10	\$0.10		approval of emission testing. Environmental air permit. Contract awarded to perform environmental acceptance tests. Waiting for EPA
	MPA 3	23		Not available			Eng. José Pagán Operation	\$0.10	\$0.10		approval of emission testing. Environmental air permit. Contract awarded to perform environmental acceptance tests. Waiting for EPA
COSTA SUR	1-1	21		Not available			Manager	\$2.00	\$2.00		approval of emission testing. Unit reached full speed not load with excitation. Phasing tests schedule for October 17. Mayor Outage
COSTA SUR	1-2	21		Not available				\$4.00		\$4.00	Repair
	1-2	21	20	Available				\$4.00	\$2.00	\$4.00	Turbocompressor replacement. Mayor Outage Repair Mayor Outage Repair
JOBOS	1-1	21	20	Available				\$2.00	\$2.00		Due for major inspection (August 2020) and speed reduction gearbox replacement.
	1-2	21	20	Not available				\$2.00	\$2.00		Alignment process. Startup testing scheduled for October 8.
YABUCOA	1-2	21	18	Available				\$2.00	\$2.00		Alignment process. Startup testing scheduled for October 22.
	1-1	21		Not available				\$2.10	\$2.10		Voltage regulator repair unit expected in service on October 15, 2021
VEGA BAJA	1-2	21		Not available				\$4.00		\$4.00	Turbocompressor major failure.
Total 18 Peaking Units		384	132	34.38%				\$36.70	\$22.40	\$14.30	Availability
	1A	27.5		Not available				\$18.00	\$18.00		Gas generator and power turbine (1B) in critical condition. Repair Cost estimate \$18 million for both units
	1B	27.5		Not available				\$10.0U	\$10.00		1A an 1B
	2A	27.5	27.5	Available							
	2B	27.5	27.5	Available			Eng. José Vázquez /				
MAYAGÜEZ	3A	27.5	25.5	Available			Eng. Waldo Córdoba				
	3B 4A	27.5 27.5	25.5	Available Not available			Plant Manager	\$0.80	\$0.80		Combustor casing crack failure. First stage nozzle issues. Pending proposal evaluation. Repair cost Estimate
	4B	27.5	25	Available				<i>ç</i> 0.00	ç0.00		\$800K.
Total Mayagüez	40	220	131	Available				\$18.80	\$18.80	\$0.00	
i otar mayaguez	1	82.5	101	Not available				\$18.00	\$18.00		Unit out of service since 2011; Combustion turbine failure; Proposal \$18 million and six months.
CAMBALACHE	2	82.5	78	Available			Eng. Herminio Arroyo /	\$6.90	\$6.90		LTSA with GE ; New Automatic Voltaje Regulator; Control System and Maintenance Services HTS
	3	82.5	77	Available			Plant Manager	\$6.90	\$6.90		LTSA with GE ; New Automatic Voltaje Regulator; Control System and Maintenance Services HTS
Total Cambalache	3	247.5	155	, tranubic				\$31.80	\$31.80	\$0.00	

Puerto Rico Electric Power Authority							Generation I	Directorat	e		
Authority							Current Status of PRE	PA Generat	ion Fleet		
							REV: NOV	2, 2021			
Power Station	Unit	Capacity (MW)	Available Capacity	Condition	Date of last major maintenance	Date of last major maintenance	Person in charge of attending findings	NME (Million)	FY22	FY23	Currents Status / Action Plan / Comments
VIEQUES	1	3	3	Available							
VIEQUES	2	3	0	Not available			Eng. José Vázquez /				Troubleshooting control system issues.
	1	2	2	Available			Eng. Waldo Córdoba				
Culebra	2	2	2	Available			Plant Manager				
	3	2	2	Available							
Total Vieques a	and Culebra	12	9								
Total Peaking & Emerger	ncy Units	1,455.5	603.0	41.43%				\$103.50	\$77.50	\$26.00	Availability

						HYDROE	LECTRICS			
Toro Negro	1-1	1.5	1.5	Available						
Toro Negro	1-2	1.5	1.5	Available						
Toro Negro	1-3	1.5	1.5	Available						
Toro Negro	1-4	4.5	0	Not Available						
Toro Negro	2	2		Not Available						Turbine inlet main valve replacement. Phasing test pending.
Yauco	1	25		Not Available			\$8.00	\$4.00	\$4.00	Pending turbine and generator major overhaul. Federal restoration funding allocation for \$8M.
Yauco	2-1	4.5	4.5	Available						Limited pending relay protection system modifications.
Yauco	2-2	4.5	4.3	Available						
Garzas	1-1	3.6	4	Available						
Garzas	1-2	3.6		Not Available		Eng. José Vázquez /				Generator bearing repair. Expected in-service on October 2021.
Garzas	2	5		Not Available		Head Division				Transmission line failure due to Hurricane Maria. Federal restoration funding approved.
Caonillas	1-1	9		Not Available		Tiedd Division	\$5.00	\$1.00	\$4.00	Station flooding failure due to Hurricane Maria. In preparation of specifications and bid process
Caonillas	1-2	9		Not Available			\$5.00	91.00	Ş4.00	documents. Federal restoration funding allocation for \$5M.
Caonillas	2	3.6		Not Available						Pending major restoration budget approvals.
Dos Bocas	1	5		Not Available						Restored generator in coordination for transportation to site.
Dos Bocas	2	5	5	Available						
Dos Bocas	3	5	0	Not Available						
Patillas	1-1	0.8		Not Available						Downstream flow risk concerns.
Patillas	1-2	0.6		Not Available						Downstream flow risk concerns.
Río Blanco	1	2.5		Not Available						Penstock major failure. Federal restoration funding approved.
Río Blanco	2	2.5		Not Available						Penstock major failure. Federal restoration funding approved.
Total Hydro		100.2	22.3	22.26%			\$13.00	\$5.00	\$8.00	

\$330.05 \$168.30
